


**Series 2-5000 Minihelic II®  
Differential Pressure Gage**

Specifications Installation &amp; Operating Instructions



"zero." Use the hex allen wrench supplied and adjust until pointer is on zero. This must be done with both pressure connections vented to atmosphere and the gage oriented in the final mounting position. Replace cover.

6. To measure positive pressure, connect tubing to port marked "HI" and vent "LO" port to atmosphere. For negative pressure measurement, connect to port marked "LO" and vent "HI" port to atmosphere. For differential pressure, connect higher

#### PANEL MOUNTED INSTALLATION

3. To surface-mount the gage, drill two 5/32" (3.97 mm) holes



54

